

Universitatea Politehnica Timisoara

Facultatea de Arhitectura

### CAIET DE SARCINI

Reparatii jaluzele vertical etajele IV, V, VI, Demisol si ASPC.

La etajul IV – Amfiteatru, salile 401 A, 401 B.

Etaj	Camera	Dim	Defecte constatate	Cant.	
Etaj 4	Amfiteatru	260 x 270	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 10 lamele material textil lipsa / deteriorate	1,00	
		260 x 210	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 6 lamele material textil lipsa / deteriorate	1,00	
		130 x 240	Mecanism interior garnisa deteriorat /	1,00	
		130 x 210	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 4 lamele material textil lipsa / deteriorate	1,00	
		130 x 210	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 2 lamele material textil lipsa / deteriorate	1,00	
		260 x 256	Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 5 lamele material textil lipsa / deteriorate	1,00	
		260 x 240	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 10 lamele material textil lipsa / deteriorate	1,00	
		130 x 240	Mecanism interior garnisa deteriorat / 2 lamele material textil lipsa / deteriorate	1,00	
		130 x 210	Mecanism interior garnisa deteriorat / 6 lamele material textil lipsa / deteriorate	1,00	
		130 x 210	Mecanism interior garnisa deteriorat / 2 lamele material textil lipsa / deteriorate	1,00	
		265 x 270	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00	
		401A	305 x 200	Mecanism interior garnisa deteriorat /	1,00
		401B	305 x 200	Mecanism interior garnisa deteriorat /	1,00

Reparatii jaluzele vertical etajele IV, V, VI, Demisol si ASPC.

La etajul V – Amfiteatru, salile 504 cabinet, 505 cabinet, 501 A, 501 B, 501 C, 501D

Etaj	Camera	Dim.	Defecte/constatate	Cant.
Etaj 5	Amfiteatru	260 x 270	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	135 x 205	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	132 x 230	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	133 x 205	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	131 x 230	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	260 x 220	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	260 x 220	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	130 x 230	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	135 x 205	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	126 x 230	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	135 x 205	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	Amfiteatru	256 x 270	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	1,00
	504 Cabinet	305 x 190	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 28 lamele material textil lipsa / deteriorate	1,00
	505 Cabinet	306 x 190	Mecanism Interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 28 lamele material textil lipsa / deteriorate	1,00
501A	310 x 200	Mecanism Interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501A	310 x 200	Mecanism Interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501A	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501A	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 20 lamele material textil lipsa / deteriorate	1,00	
501B	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501B	310 x 200	Mecanism Interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501B	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00	
501B	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 30 lamele material textil lipsa / deteriorate	1,00	

Etaj	Camera	Dim	Defecte constatate	Cant.
	501C	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	501C	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	501D	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	501D	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	501D	310 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 5 lamele material textil lipsa / deteriorate	1,00

La Etajul VI – sala 600, demisol si ASPC

Etaj	Camera	Dim	Defecte constatate	Cant.
Etaj 6	600	305 x 270	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	600	320 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate /	1,00
	600	315 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 3 lamele material textil lipsa / deteriorate	1,00
	600	320 x 200	Mecanism interior garnisa deteriorat / Lant conectare lamele lipsa / deteriorat / Greutati lamele material textil lipsa / deteriorate / 2 lamele material textil lipsa / deteriorate	1,00
Demisol		305 x 190	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	3,00
		305 x 190	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	3,00
SPC		354 x 208	Garnisa superioara deteriorata complet / lamele material textil deteriorate complet	3,00
total eur				
total lei				53buc
				53 buc

Intocmit,

Ing. Cezar Oprea

